

- Project Directive 45-9, Cont. 2, TDEA 2736, July
- Approved For Release 2009/07/07 : CIA-RDP68B00724R000200310032-1
- 7-1. Lower hatch seal sticks. Article 384. Total time on item - Unknown. Reason for failure - Unknown. Negative.
- 7-2. Fuel Pressure Indicator, Part Number - SP-290-60K, Serial Number - None. Fuel pressure reads 30 PSI from take-off to plus 1 hour then 20 PSI. Article 384. Total time on item - Unknown. Reason for failure - Unknown. Negative.
- 7-3. BDH1 Indicator, Part Number - SP-248-745, Serial Number 152. Indicator slumps 2 to 3 degrees from preset heading while aircraft is turning to new heading. Article 372. Total time on item - Unknown. Reason for failure - Unknown. Negative.
- 7-4. Antenna Tuner, Part Number - 490T-1, Serial Number - 154. Single side band and birdwatcher inoperative. Article 372. Total time on item - Unknown. Reason for failure - Unknown. Negative.
- 7-5. Antenna Tuner, Part Number - 490T-1, Serial Number - 160. Birdwatcher did not chirp properly. Article 372. Total time on item - Unknown. Reason for failure - Unknown. Negative.
- 7-6. Reducer, Part Number - F-17130-9, Serial Number - L-12. Secondary pressure reducer of the oxygen system crept beyond limits. Article 349. Total time on item - Unknown. Reason for failure - Unknown. Negative.
- 7-7. Birdwatcher Air Sensor, Part Number - SP-71031, Serial Number - 021. Birdwatcher chirped 3 times for below 80 knots when actual airspeed was 95 knots. Article 372. Total time on item - Unknown. Reason for failure - Unknown. Negative.
- 7-8. Transponder, Part Number - SP-97573-302, Serial Number - Unknown. IFF inoperative. Article 342. Total time on item - Unknown. Reason for failure - Unknown. Negative.
- 7-9. Fuel Transmitter, Part Number - SP-H222-C, Serial Number - 374305-M1. Fuel counter slow. Article 342. Total time on item - 199.0 hours. Reason for failure - Unknown. Negative.
- 7-10. Cabin and Q-Bay Altitude Selector Valve, Part Number - SP-11-254-8, Serial Number - Unknown. Q-Bay and cabin pressure same. Article 342. Total time on item - Unknown. Reason for failure - Unknown. Negative.
- 7-11. ARC-34, Stock Number - 5821-505-0945, Serial Number - Unknown. UHF receiver weak. Article 348. Total time on item - Unknown. Reason for failure - Unknown. Negative.
- 7-12. ARC-34, Stock Number - 5821-505-0945, Serial Number - F9533. UHF receiver inoperative. Article 348. Total time on item - Unknown. Reason for failure - Unknown. Negative.
- 7-13. Quick Disconnect to Faceplate, Part Number - SPF-421, Serial Number - None. Unable to transmit on normal wiring. Bypass OK. Article 342. Total time on item - Unknown. Reason For failure - Unknown. Negative.

25 YEAR
RE-REVIEW